


# How-to go into Off-duty


## How-to go into Off-duty

### Step-by-step guide


1. From the main Menu, select the HOS option.



2. From the US-8 screen (Short-haul 100 if you're local) in HOS, touch "Off-duty"




3. Next touch "End of Shift" if your duty day is complete, "Break" if you are taking a break, or "Other" for any other circumstance. In this example we will touch "Break".



# How-to go into Off-duty

4. Review the details on the next screen. If correct, touch "Submit".

A screenshot of a mobile application interface for logging off-duty status. The screen has a dark background. At the top left is a button labeled "<< Back". At the top right is a button labeled "Submit", which is highlighted with a red rectangular border. Below these are four rows of input fields: "Time" with a value of "10:57" and a "More..." button; "Status" with a value of "Off-duty"; "Location" with a value of "Salt Lake City,UT"; and "Remark" with a value of "Break". At the bottom of the screen is a status bar with a "Menu" button, a green "HOS" indicator, the time "09:43", a clock icon, a signal strength icon, the time "10:59", and a battery icon.

You are now in Off-duty, and on break.

## Related articles

- [How does the unit warn for Personal Use limits?](#)
- [How-to send HOS ELD logs to Enforcement Officer for Roadside Audit](#)
- [Why do I see events from other trucks on my log for today?](#)
- [Who can Certify an HOS log?](#)
- [What is Required to Trigger an Auto-Arrival \(Workflow\)?](#)

[Back to The Top](#)

[Home](#)