WEB 6.12

- · Replaced set 'Manual VIN' checkbox to prevent JBUS from updating VIN

 - Checkbox has been removed that prevented updating of VIN by Vehicle's JBUS.
 Instead, if user updates the VIN manually via web portal the Manual VIN flag will be set automatically indicating that the VIN was entered manually.
 - BUT, if the vehicle's JBUS reports a VALID VIN it will replace the manually entered VIN.
- NEW report: Vehicle Malfunctions (see "Help Doc: Vehicle Malfunctions")
 - o Provides summary and detail when the ELD records a vehicle malfunction as outlined in FMCSA ELD rules set.
- NEW report: DT Fuel Sensor (see "Help Doc: DT Fuel Sensor")
 - o Provides aggregate summary and individual detail when the ELD records a DT Fuel Sensor events (DT Fuel Fill, DT Fuel Drain, DT Fuel Update with tank levels (via Position update)).
- IMPROVED: Set Destination based on Pin Location not nearest address
- IMPROVED: General performance improvements of some reports and larger data request
- IMPROVED: Standard Output file to FMCSA