


# How-to Calibrate Your Screen

## How-to Calibrate Your Screen



### Step-by-step guide

This procedure is for the DT4000 Rev 6 and lower devices:



1. If your screen is responding to touch: Touch the "Calibrate" icon.



2. Touch on the crosshair target. It should move around the screen 4 times.



# How-to Calibrate Your Screen



Your screen should now be calibrated.

1. If your screen is not responding or is too far out of calibration to touch the icon:
  - a. Hold the PHYSICAL menu button down for 10 seconds while logged in. The physical menu button can be found on the monitor unit but below the screen itself.
  - b. New Style



# How-to Calibrate Your Screen

c. Old Style



- d. The calibration screen should now come up.
- e. Touch the crosshair targets in order to calibrate.
2. Alternatively you can plug a mouse into the USB port and select the calibration icon.
  - a. Touch the crosshair targets in order to calibrate.

## Related articles

- [How-to send HOS ELD logs to Enforcement Officer for Roadside Audit](#)
- [Helpful Pages for New Customers](#)
- [My touchscreen is not responding. How can I fix it?](#)
- [How-to Calibrate Your Screen](#)
- [How-to turn a smartphone into your ELD display screen](#)

[Back to The Top](#)

[Home](#)