

Vehicle Inspection

The Vehicle Inspection report provides Vehicle Inspection Reports made on the in-cab unit, enabling web portal users to record any repair information when there are vehicle defects recorded. The report can be run for any vehicle or vehicle group.

- [Configure Report](#)
- [Edit DVIR Entry \(for Repairs\)](#)
- [DVIR Workflow](#)

Configure Report

To configure the columns of the spreadsheet, click Columns at the bottom left corner of the screen, and choose which columns you would like to view. You can also move the tiles around to customize the order of the columns. You can select to view only those DVIR entries that have defects by selecting [Has Defect].

DVIR Report

Vehicle: Vehicle Group: Include Reviewed: Today Get Results

Show Detail: Has Defect: Export To Excel

Actions	Report Date	Vehicle	Driver	Location	Vehicle Condition	Repair Status	Last Update	Repair Rate	Repairs By	Review Date	Reviewed By	Remarks
	2/13/20 2774	Gr	IC	3.7 NE of Ontario	Operational	Unknown	2/13/20					
	2/13/20 2754	S'		3.8 NW of Huron	Operational	Unknown	2/13/20			2/13/20	S	IS
	2/13/20 2604	DK		2.4 E of Fairland	Operational	Unknown	2/13/20					
	2/13/20 2399	M		F1 3.7 NE of Reno	Operational	Unknown	2/13/20					
	2/13/20 2338	CI		N1 3.4 N of West V	Operational	Unknown	2/13/20					
	2/13/20 2338	CI		N1 3.4 N of West V	Operational	Unknown	2/13/20					
	2/13/20 2707	S		M 2.8 NE of Nellis	Operational	Unknown	2/13/20			2/13/20	S	AN
	2/13/20 2852	Jr		ER 1.4 NW of Loran	Operational	Unknown	2/13/20					
	2/13/20 2416	Jr		E 2.4 NE of Pasco	HasDefect	Unknown	2/13/20					
	Defect Description: OIL ON BRAKE CALIPER											
	2/13/20 2808	Jr		A1 1.5 N of Morris	Operational	Unknown	2/13/20					
	2/13/20 2655	Gr		3.2 NE of Ontario	Operational	Unknown	2/13/20			2/13/20	G	
	2/13/20 2612	C		V 2.4 E of Fairland	Operational	Unknown	2/13/20					
	2/13/20 2824	N		RD 1.5 NE of State	Operational	Unknown	2/13/20			2/13/20	M	IC
	2/13/20 2492	M		C 2.6 NE of Isleta	Operational	Unknown	2/13/20					
	2/13/20 2379	D		D 13.5 W of Warr	Operational	Unknown	2/13/20			2/13/20	D	D
	2/13/20 2356	N		R, P 2.7 NE of Tacon	Operational	Unknown	2/13/20					
	2/13/20 2858	E		E 2.3 NE of Santa	Operational	Unknown	2/13/20					
	2/13/20 2780	D		N 2.7 NE of Nellis	Operational	Unknown	2/13/20			2/13/20	D	AN
	2/13/20 2344	M		M 1.2 NW of Toller	Operational	Unknown	2/13/20					
	2/13/20 2781	B		1.1 W of Troy J	Operational	Unknown	2/13/20					
	2/13/20 2536	W		T 6.1 SE of Jarom	Operational	Unknown	2/13/20					
	2/13/20 2597	R		R 6.3 E of Cheyan	Operational	Unknown	2/13/20					
	2/13/20 2686	Jr		W 2.4 SE of Meridi	Operational	Unknown	2/13/20			2/13/20	Jr	W
	2/13/20 2727	IC		3.4 E of Bland	Operational	Unknown	2/13/20					

Edit DVIR Entry (for Repairs)

When you have defects reported in your DVIR entries, you can make edits to the repair information by clicking on the [blocked URL](#) icon in the **Actions** column of the spreadsheet.

From this window, you can also click on the Location where the DVIR occurred. This will open up a map in your browser in a new tab so you can see the exact location of where the DVIR was entered.


You can edit the **Repaired By**, **On** (Date of Repair), **Repairs Performed** or **No Repairs Needed** (whether repairs were completed or if they were not necessary), and enter any remarks about the repair.

[blocked URL](#)

Once you are satisfied with the DVIR entry and any edits, click [Submit].
To clear the Repair Info, click [Clear Form].

DVIR Workflow

Vehicle Inspection



Legend:

1	Actions	Report Date	Vehicle	Driver	Trailers	Location	Latitude	Longitude	Vehicle Condition	Repair Status	Defect Count	Last Updated	Odometer	Repair Date	Repair By	Review Date	Reviewed By	Remarks
		7/24 12:00	54071	SHAVER, FRANK, 355893	49460,49237	3.0 SE of Ashland, VA	37.7243767	-77.44821	Operational	Unknown	0	7/24 12:00	683219.6					
2		7/24 11:26	76101	DAVILA, RUBEN, 389807	12471,24806	2.5 NW of Channelvie	29.8102818	-95.12845	HasDefect	Unknown	1	7/24 11:27	364645.9					
	Defect Description		Remarks															
	Trailer-12471: Lights		NEEDS NEW PIG TAIL CONNECTOR															
3		7/24 11:26	76101	DAVILA, RUBEN, 389807	12471,24806	2.5 NW of Channelvie	29.8102818	-95.12845	HasDefect	Performed	1	7/24 11:04	364645.9	7/24	John Doe			Order #: 1234 New pig tail connect
	Defect Description		Remarks															
	Trailer-12471: Lights		NEEDS NEW PIG TAIL CONNECTOR															
4		7/24 11:26	76101	DAVILA, RUBEN, 389807	12471,24806	2.5 NW of Channelvie	29.8102818	-95.12845	HasDefect	NotRequired	1	7/24 11:04	364645.9	7/24	John Doe			Repair not required
	Defect Description		Remarks															
	Trailer-12471: Lights		NEEDS NEW PIG TAIL CONNECTOR															
5		7/24 11:26	76101	DAVILA, RUBEN, 389807	12471,24806	2.5 NW of Channelvie	29.8102818	-95.12845	Operational	Performed	1	7/24 11:04	364645.9	7/24	John Doe	7/25 10:26	DAVILA, RUBEN, 389807	Order #: 1234 New pig tail connect
	Defect Description		Remarks															
	Trailer-12471: Lights		NEEDS NEW PIG TAIL CONNECTOR															